

कार्यालय अधिशासी अभियन्ता
प्रान्तीय खण्ड, लोक निर्माण विभाग
नैनीताल

ई-मेल-eeepdwntl@gmail.com

पत्रांक :- 475/BE

दिनांक :- 02/03/2023


Building Safety Certificate

This is certified that the school building of **Birla Vidya Mandir, Nainital** found well maintained and running in good condition as on date. It has been observed on our visual inspection that the existing building seem to be safe at present under normal circumstances for the a year 2023-24.

Extra precautions are needed to be taken in the school because the campus of **Birla Vidya Mandir** is located in **Sher Ka Danda**, a geologically sensitive hill in the Nainital. In Present cracks are visible in the floor and walls of building therefore , experts opinion recommended early. As per the enclosed Structural Engineer Report the building of school are ^{CIA} ~~running~~ running safe due to good maintenance set up in the school.

Encl :- As above Structural Engineer Report.


Principal
Birla Vidya Mandir
Nainital-263 001 (Uttarakhand)


22/02/23

Executive Engineer
Provincial Division
Nainital